

# AMD Ryzen 9 9950X processor 4.3 GHz 80 MB L2 & L3 Box



Model: 100-100001277WOF

Manufacturer: AMD

EAN: 730143315272

Product Code: 1249661

## R12,486

Discrete graphics card: No | Processor operating modes: 64-bit | Memory channels: Dual-channel | Processor family: AMD Ryzen™ 9 | Maximum internal memory supported by processor: 192 GB | On-board graphics card: Yes | Processor manufacturer: AMD | Supported instruction sets: SSSE3 | Processor threads: 32 | Supported instruction sets: AVX | Supported instruction sets: AVX 2.0 | Supported instruction sets: SSE4.1 | Supported instruction sets: SSE2 | Processor cache type: L2 & L3 | Processor model: 9950X | ECC: Yes | Processor cache: 80 MB | Supported instruction sets: AVX-512 | Supported instruction sets: SSE4.2 | Supported instruction sets: AES | Supported instruction sets: SSE3 | Supported instruction sets: SSE | Processor cores: 16 | Memory types supported by processor: DDR5-SDRAM | Cooler included: No | On-board graphics card model: AMD Radeon | Processor lithography: 4 nm | Memory clock speeds supported by processor: 5600 MHz | On-board graphics card base frequency: 2200 MHz | Processor socket: Socket AM5 | Thermal Design Power (TDP): 170 W | Memory clock speeds supported by processor: 3600 | Processor boost frequency: 5.7 GHz | Processor base frequency: 4.3 GHz | Processor generation: AMD Ryzen 9000 Series | Discrete graphics card model: Not available | PCI Express slots version: 5.0 | Non-ECC: Yes | Warnings:

The product information provided is for reference purposes only. Technical specifications, photos, descriptions and prices may change without prior notice. The manufacturer and seller are not responsible for possible data discrepancies or typographical errors. We recommend checking the current information before purchasing.

Processors contain electronic components that may be harmful to the environment. Do not dispose of in the regular trash. | Warnings: Use appropriate processor mounting equipment to avoid mechanical damage. | Warnings: Processors can get very hot during operation. Make sure they are adequately cooled.