




Lexmark Fuser Maintenance Kit for MS82X SVC

Model: 41X2234

Manufacturer: LEXMARK

EAN: 5706998284716

Product Code: 394045

R8,330

The product information provided is for reference purposes only. Technical specifications, photos, descriptions and prices may change without prior notice. The manufacturer and seller are not responsible for possible data discrepancies or typographical errors. We recommend checking the current information before purchasing.

itworkup.co.za | sales@itworkup.co.za | +27 (11)541-9950