



Greenblue 46003 Black LCD Battery Wi-Fi



Model: GB522

Manufacturer: GREENBLUE

EAN: 5902211105220

Product Code: 610596

R1,500

Measuring functions trend display: Barometer | Measuring functions: Indoor thermometer | Power source: Battery | Measuring functions trend display: Thermometer | Measuring functions: Outdoor hygrometer | Measuring functions: Indoor hygrometer | Protection features: Water resistant | Battery voltage: 1.5 V | Weather forecast: Yes | Built-in display: Yes | Connectivity technology: Wired & Wireless | Temperature measurement range (inside) (T-T): -20 - 60 °C | Humidity measuring range (inside) (H-H): 20 - 95% | Wi-Fi: Yes | Alarm function: Yes | Temperature measurement units: F | Number of batteries (sensor): 2 | Weather station extremum data: Barometer | Moon phase: Yes | Measuring functions trend display: Hygrometer | Battery included: No | Product colour: Black | Clock/Date display: Yes | Weather station extremum data: Hygrometer | Weather station extremum data: Thermometer | Temperature measurement units: °C | Measuring functions: Outdoor thermometer | Battery type: LR06 | Display type: LCD | Manual: Yes | Clock function: Yes | Warnings: The product contains electronic components which may be hazardous if misused. | Warnings: Do not expose to prolonged moisture. | Warnings: Keep away from children to avoid the risk of swallowing small parts. | Outdoor sensors range: 60 m | Temperature measurement range (inside) (T-T): -4 - 140 °F | Number of outdoor sensor: 1 | Temperature measurement range (outside) (T-T): -40 - 70 °C |

The product information provided is for reference purposes only. Technical specifications, photos, descriptions and prices may change without prior notice. The manufacturer and seller are not responsible for possible data discrepancies or typographical errors. We recommend checking the current information before purchasing.

itworkup.co.za | sales@itworkup.co.za | +27 (11)541-9950

Outdoor sensor: Yes | Humidity measuring range (outside) (H-H): 20 - 95% | Temperature measurement range (outside) (T-T): -40 - 158 °F

The product information provided is for reference purposes only. Technical specifications, photos, descriptions and prices may change without prior notice. The manufacturer and seller are not responsible for possible data discrepancies or typographical errors. We recommend checking the current information before purchasing.

itworkup.co.za | sales@itworkup.co.za | +27 (11)541-9950