

AMD Ryzen 9 9950X processor 4.3 GHz 80 MB L2 & L3 Tray



Model: 100-000001277

Manufacturer: AMD

Product Code: 937090

R10,095

Processor generation: AMD Ryzen 9000 Series | Processor base frequency: 4.3 GHz | ECC: Yes | Memory channels: Dual-channel | Non-ECC: Yes | Processor family: AMD Ryzen™ 9 | Processor model: 9950X | Processor cache: 80 MB | Discrete graphics card model: Not available | Processor cores: 16 | Processor lithography: 4 nm | Discrete graphics card: No | PCI Express slots version: 5.0 | Processor cache type: L2 & L3 | Supported instruction sets: SSE4.1 | Supported instruction sets: SSE2 | Memory clock speeds supported by processor: 5600 MHz | Thermal Design Power (TDP): 170 W | Supported instruction sets: AVX-512 | Supported instruction sets: SSE3 | Supported instruction sets: SSE | Memory clock speeds supported by processor: 3600 MHz | On-board graphics card base frequency: 2200 MHz | Cooler included: No | Processor socket: Socket AM5 | Supported instruction sets: SSE4.2 | Supported instruction sets: AES | Processor manufacturer: AMD | Processor boost frequency: 5.7 GHz | Maximum internal memory supported by processor: 192 GB | Memory types supported by processor: DDR5-SDRAM | Processor operating modes: 64-bit | Supported instruction sets: AVX | On-board graphics card model: AMD Radeon | Supported instruction sets: AVX 2.0 | Processor threads: 32 | Supported instruction sets: SSSE3 | On-board graphics card: Yes | Warnings:

Processors contain electronic components that may be harmful to the environment. Do not dispose

The product information provided is for reference purposes only. Technical specifications, photos, descriptions and prices may change without prior notice. The manufacturer and seller are not responsible for possible data discrepancies or typographical errors. We recommend checking the current information before purchasing.

itworkup.co.za | sales@itworkup.co.za | +27 (11)541-9950

of in the regular trash. | Warnings: Use appropriate processor mounting equipment to avoid mechanical damage. | Warnings: Processors can get very hot during operation. Make sure they are adequately cooled.